DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: <u>SF/ALA</u> Rte: <u>80</u> PM: <u>13.2/13.9</u>

File #: 69.12

DAILY PROJECT JOURNAL

Prime Contractor: American Bridge/Fluor Enterprises, a JV Report No: DPJ-000507 **Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island Dated: 29-Nov-2007

Location: Changxing Island, Shanghai, China

Submittals(New / Total): CWR'		CVIK S. /	HSR's: /	NCR's: /	
tem Title	<u> </u>	Detail			
Mee	tings attended		7:15 Attended weekly METS conference call. The following issues were discussed:		
		- submitta	- submittals – we've had many recently which have only 14 day review time.		
		- Tower: I	- Tower: Distortion control for the Mock up skin plates is still a top issue as		
		is the high	is the high number of HSRs and CWR's recently.		
		- OBG: D	- OBG: Dave McClary and Steve Lawton discussed the UT procedure		
		yesterday.	yesterday. Macros have been taken from the weld trial and evaluated by		
			and Ct. Agreed that overlap e	xists and that there are undersized	
		welds.			
			sh discussed status of cables ar		
. Mee	tings attended		:15 Attended Owners Meeting.		
			on of Production/QC independ	<u>*</u>	
		ZPMC pro	oduction department be represe	ented at daily meeting at 13:00.	
		- ABF wi	ll ask Mr Ding to attend the Da	aily meeting and Mr. ChinBin to	
		attend the	owner's meeting.		
			on of the purpose of the daily r	meeting and of the weekly owner's	
		meeting.			
		-ABF inid welding se	licated that they are currently we equence.	vorking on tower mock-up fab	
		_	_	me for the distortion control plan	
			wer skin plates.	•	
			apes which have lost tracability	: ABF indicates that these are	
			-	be identified and those which can	
			ntified. As of yet, nothing has		
			licated that they will stand by the		
			e of weld trial #2.		
		=	licated that they met with ZPM	C vesterday and held a "Heat	
				to a question regarding what ABF	
		_	ensure that ZPMC does not pe		

DAILY PROJECT JOURNAL

(Continued Page 2 of 2)

straightening".

- Steve Lawton of ABF indicated that he had discussed with Mr. Lu of ZPMC recently regarding the requirements of the MFSQA.
- Status of outstanding NCR's was discussed.
- Scheduling of work: ABF/ZPMC indicated that they will give Caltrans at least 1 day notice when night shift work will take place

3 Meetings attended 13:00 Attended Daily meeting: the following items were discussed:

- ZPMC inquired regarding RT Film location a meeting will be held tomorrow morning at 8:00 between John Kinsey of Caltrans and ZPMC's RT technicians and ABF's QC.
- Jim Merrill inquired what is the status of how ABF plans to do RT for heavy plate. ABF indicated that Steve Lawton is working on this right now.
- ZPMC indicates that the 89m diaphragm has finished being machined and will be shipped back to Changxing island during the next 7 days.
- ZPMC indicated that they will be bending floor beam flange plates for the OBG tomorrow at WUXI.
- ZPMC's night shift is from 11:00 pm to 7:00 am
- Tower: Caltrans has received several CWR's for rev 4 repairs. Caltrans expressed concern that these do not return to us at "rev 5" CWRs. ZPMC clarified that the current packet of weld repairs represent weld defects in welds which had been performed with the skin horizontal (rather than in the 80 degree position)

Mr Ryan Smith of Caltrans, reiterated that Heat straightening is not a means of production.

Mr Jim Merrill also noted that diaphragm fitup may become an issue of skin-plate straightness is not tightly controlled.

Inspected By: Dautermann, Peter Quality Assurance Inspector

OA Reviewer

Reviewed By:

Wahbeh, Mazen